

Galion, Ohio 44833

hally be in place

PHONE 419-468-1680 FAX 419-468-7620

February 23, 1996

Michael Traugh School Superintendent 200 W. Church Galion, OH 44833

Dear Mike,

Enclosed is some information relating to football field towers. Per our previous discussion, it appears the City will no longer be able to provide maintenance for these towers. However, please feel free to contact us if we can be of assistance in the transition to a contractor to provide this service.

Sincerely,

Phil Honsey City Manager

PH:cd

Enclosure



OHIO BUREAU OF EMPLOYMENT SERVICES

145 South Front Street P.O. Box 1618 Columbus, Ohio 43216-1618

Debra R. Bowland Administrator

George V. Voinovich Governor

April 2, 1996

Larry Mullins, Assistant Superintendent Galion City Schools 200 West Church Street Galion, Ohio 44833

Dear Mr. Mullins:

This is a follow-up to our conversation last week as well as my consultation inspection of November, 1995.

Based on OSHA standards, the climbing of the light poles at the football field is not in compliance. I have discussed the issue with a representative of Federal OSHA, who is researching the problem for me.

I apologize for the delay, however, this is a complex situation which needs attention. I will get back to you as soon as I have an answer.

Please call me if you have further problems.


Sincerely,

Jodi Mains, Safety and Health Consultant

Occupational Safety and Health

JM/bw

File



RINEHART TOWER SERVICE, INC.

P.O. Box 360773

Columbus, Ohio 43236-0773

Telephone: (614) 868-1911 Fax: (614) 868-1956

May 6, 1996

Galion City Schools 200 West Church Street Galion, Ohio

Attn: David Chandler

On April 16, 1996 Rinehart Tower Service, Inc. inspected the football field towers. Our standard tower inspection and maintenance report was completed. We recommend the following to be done on each tower.

- (1) Install Safety Climbing Device to meet OSHA standards.
- (2) Install 6 ft. High Fence around tower for security.
- (3) Install new Lighting System to reduce wind leading.
- (4) Reduce height of tower or replace damaged tower legs.
- (5) Install Tower Grounding to protect tower lighting system.

Lay & Rindont

(6) Annual Inspection & Written Inspection Report to assure that everything is in good condition and working properly.

Sincerely,

Lany E. Rinehart

President

LER: finc co: file

Reaching New Heights In Communication



Quotation

Quote Number: 1115 Quote Date: May 14, 1996 Page: Quoted to:

Galion City Schools 200 W. Church Street Galion, OH 44833

Site Data:

Tower Site Football Field Galion, Ohio Attn: David Chandler

Customer ID	Good Thru	Payment Terms ·	Sales Rep
C292	6/13/96	Net 10 Days	Larry E. Rinehart

Quantity	Unit	Description	Extension
		Replace damaged Tower Legs (section #8) on existing towers.	13,000.00
		Rinehart Tower Service, Inc. strictly adheres to the standards and practices adopted by the Occupational Safety and Health Administration (OSHA).	
		Rinehart Tower Service, Inc. will furnish materials for replacing damaged tower legs, all labor, tools, rigging & equipment necessary to complete the job.	

Subtotal SalesTax Total 13000.00

Reaching New Heights In Communication



Quotation

Quote Number: 1113 Quote Date: May 14, 1996 Page:

1

Quoted to:

Galion City Schools 200 W. Church Street Galion, OH 44833

Site Data:

Tower Site Football Field Galion, Ohio Attn: David Chandler

Sales Rep Payment Terms Good Thru Customer ID

Customer ID		Good Thru Payment Terms				
C29		6/13/96 Net 10 Days Larry E		E. Rinehart		
Quantity Unit		Description			Extension	
		Install (6) Safetower).	6,864.00			
		towar to the to	Install a 3/8" safety cable from base of each tower to the top of each tower with mounting brackets to meet OSHA requirements.			
		Rinehart Tower to the standards Occupational Sa (OSHA).				
		Rinehart Tower Service, Inc. will furnish (6) safety climbing devices, all labor, tools, rigging & equipment necessary to complete the job.				

Subtotal SalesTax Total

6864.00

Reaching New Heights In Communication



Quotation

Quote Number: 1112 Quote Date: May 14, 1996 Page: Quoted to:

Galion City Schools 200 W. Church Street Galion, OH 44833

Site Data:

Tower Site Football Field Galion, Ohio Attn: David Chandler

Customer ID	Good Thru	Payment Terms	Sales Rep
C292	6/13/96	Net 10 Days	Larry E. Rinehart

C29	92		6/13/96	Net 10 Days	Larry E. Rimenarc	
Quantity	Unit	Description				Extension
		Inst (on	all (6) Grower to	858.00		
		Inst	all (1) 6 f	t. copper ground rod in of tower.	the	
		Cadw	reld (1) copy cop of ground	per cable from base of t ding rod.	tower	
		+ +	chart Tower the standard upational Sa HA).			
		Rinehart Tower Service, Inc. will furnish (6) ground rods, copper cable, cadweld, all labor, tools, rigging & equipment necessary to complete the job.				

Subtotal SalesTax Total 858.00

Reaching New Heights In Communication



Quotation

Quote Number: 1114 Quote Date: May 14, 1996 Page: 1 Quoted to:

Galion City Schools 200 W. Church Street Galion, OH 44833

Site Data:

Tower Site
Football Field
Galion, Ohio

Attn: David Chandler

Customer ID		Good Thru	Payment Terms	Saies Rep
		6/13/96	Net 10 Days	Larry E. Rinehart
Quantity Unit			Description	Extension
		Relamping existing	ng tower lights (al	1,700.00

C232			Description				
Quantity	Unit			Extension 1,700.00			
		Relamping exist towers.) Only d be replaced.	elamping existing tower lights (all owers.) Only defective or burnt lamps will e replaced.				
		11+	Service, Inc. strictly adheres s and practices adopted by the fety and Health Administration				
		1	Service, Inc. will furnish ups, all labor, tools, rigging essary to complete the job.				

Subtotal SalesTax Total 1700.00

Reaching New Heights In Communication



Quotation

Quote Number: 1116 Quote Date: May 15, 1996 Page: 1 Quoted to:

Galion City Schools 200 W. Church Street Galion, OH 44833

Site Data:

Tower Site Football Field Galion, Ohio Attn: David Chandler

			101		
Cust	omer ID	Good Thru	Good Thru Payment Terms		Rep
C2				Larry E	. Rinehart
Quantity	Unit		Description		Extension
		1 . 11 1 d ~ h +	ower Lighting from to ing provided by custo usco Sports - Lightin	mer.	5,747.00
		This price is the price for each tower if all towers are not done at the same time.			
		Tower Lighting witower to base of system.	ll be installed from tower and tied into e	top of existing	
		to the standards	rvice, Inc. strictly and practices adopted ty and Health Adminis	g by the	
		Rinehart Tower Se	rvice, Inc. will furr	nish tools,	

misc. bracketing hardware, all labor, tools, rigging & equipment necessary to complete the

Subtotal SalesTax Total 5747.00

5747.00

job.

Reaching New Heights In Communication



Quotation

Quote Number: 1117 Quote Date: May 15, 1996 Page: 1 Quoted to:

Galion City Schools 200 W. Church Street Galion, OH 44833

Site Data:

Tower Site
Football Field
Galion, Ohio
Attn: David Chand

Attn: David Chandler

Customer	ID	Good Thru	Payment Terms Sales		es Rep	
C292	C292 6/14/96 Net 10 Days Lar		Larry E	rry E. Rinehart		
Quantity U	Quantity Unit		Description		Extension	
	Remoinst (light Ring Occ (OS	tall new lighting from sprice is that ing on all the standards upational Saha). The chart Tower sc. bracketing and a equipment of the standards and the standards are spracketing as a spracketing as a spracketing and the standards are spracketing as a sprac	Tower Lighting from too hting provided by custon Musco Sports - Lighting he price for installing I towers at the same tin Service, Inc. strictly s and practices adopted fety and Health Adminis Service, Inc. will furn g hardware, all labor, ment necessary to compl	me. adheres by the tration ish tools,	29,585.00	
				total	29585.00	

Subtotal SalesTax Total 29585.00